

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	5489	DATE	June 12. 2024
MANUFACTURE	Topre Corporation		
DESCRIPTION OF DEFECT	Some large vehicles with refrigerator, amount of sealant were too much at the joint of Corner rail and the Rivet cover,so the joint between the Rivet cover and the Corner rail were insufficient.Therefore, due to the load during driving, the Rivet cover may lift from the Corner rail.In the worst case, the Rivet cover may remove from the Corner rail,and may obstruct the traffic of other vehicles. ① For vehicles that have been inspected, we carry out the following improvements. 1) If there are no abnormalities, rivet the front and center of the Rivet cover. 2) If there are abnormalities, replace the Rivet cover and rivet both ends and the center. ② For vehicles that have not been inspected, we carry out the following improvements. 1) If there are no abnormalities, rivet the both ends and the center of the Rivet cover. 2) If there are abnormalities, replace the Rivet cover and rivet both ends and the center.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2KG-CVR60C	GIGA	2021	1
2KG-CXY77CJ		2018~2022	17
2KG-CYJ77C		2017~2022	212
2KG-CYJ77CA		2017~2022	145
2KG-CYL77C		2017~2022	74
2KG-CYL77CA		2018~2022	34
2KG-CYL77CZ		2017~2021	3
2KG-CYY77C		2018~2021	5
2KG-CYY77CJ		2021	1
2KG-CYY77CY		2018~2022	91
2PG-CXY77CJ		2021	1
2PG-CYJ77C		2017~2022	72
2PG-CYJ77CA		2017~2022	52
2PG-CYL77C		2018~2022	37
2PG-CYL77CA		2017~2021	7
2PG-CYL77CZ		2019~2021	4
2PG-CYY77C		2018~2020	2
2PG-CYY77CY		2018~2021	10
PDG-CYL77V8		2019	1
QKG-CXE77B		2017	4
QKG-CXY77BJ		2017	10
QKG-CYJ77B		2017~2019	71
QKG-CYJ77BA		2017~2018	36
QKG-CYJ77BZ		2017	2
QKG-CYL77AZ		2017	1
QKG-CYL77B		2017	35
QKG-CYL77BA		2017	6
QKG-CYL77BZ		2017~2018	7
QKG-CYY77B		2017	2
QKG-CYY77BY		2017	17
QPG-CYJ77B		2017	4
QPG-CYL77B		2017	4
QPG-CYL77BA		2017	1
2PG-FSR90T2	FORWARD	2020	1

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2PG-FTR90V2	FORWARD	2018~2021	22
2PG-FVR90U2		2020	1
2RG-FSR90T2		2021	1
SPG-FSR90T2改		2017	2
2RG-FTR90V2		2018~2021	7
LKG-FTR90T2		2017	6
LPG-FTR90T2		2017	2
QKG-FTR34T2		2017	2
QKG-FVZ34U2		2017	1
2DG-FN1AGG	HINOPROFIA	2018	2
2DG-FQ1AJG		2017~2021	30
2DG-FQ1AJJ		2018~2022	21
2DG-FR1AHG		2017~2022	59
2DG-FR1AHJ		2017~2022	48
2DG-FR1EHG		2019~2020	6
2DG-FR1EHJ		2018~2021	6
2DG-FS1AHG		2018~2022	6
2DG-FS1AHJ		2017~2021	8
2DG-FW1AHG		2017~2022	221
2DG-FW1AHJ		2017~2022	152
2DG-FW1AJG		2017~2020	2
2DG-FW1AJJ		2018~2022	6
2DG-FW1EHG		2017~2021	22
2DG-FW2EHJ		2020	1
2KG-FH1AGA		2018	1
2KG-FH1AGG		2021	1
2NG-FW1AHH		2021	1
2PG-FW1AHG		2018~2020	2
2RG-FR1AHG		2017~2018	3
BKG-FW1EXYJ		2019	1
LKG-FW1EXBJ		2019	1
PK-FR1EXWG		2019	1
QKG-FW1EXEG		2017	2
QPG-FQ1EWEG		2017	7
QPG-FQ1EWEJ		2017	5
QPG-FR1EXEG		2017	6
QPG-FR1EXEJ		2017	11
QPG-FW1EXEG		2017	35
QPG-FW1EXEJ		2017~2018	23
QPG-FW1EYEG		2017	5
QPG-FW1EYEJ		2017	1
QPG-FW1EZEG		2017	1
2DG-GK2ABA	HINORANGER	2018~2019	5
2KG-FE2ABG		2019	1
2KG-GD2ABG		2019	4
2PG-FE2ABG		2018~2021	17
2PG-FE2ACG		2021	1
QKG-FE7JPAG		2017	1
QKG-FE7JUAG		2017	3
2KG-FS74HZ	FUSOSUPERGREAT	2021~2022	4
2KG-FU74HZ		2021	2
2PG-FS74GY		2018~2022	9
2PG-FS74GZ		2020	3

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2PG-FS74HY	FUSOSUPERGREAT	2017~2018	3
2PG-FS74HZ		2017~2022	190
2PG-FS75GY		2022	1
2PG-FS75HZ		2017~2022	134
2PG-FU74HZ		2017~2022	59
2PG-FU75HZ		2017~2021	17
2PG-FV74HZ		2019~2022	7
2PG-FY74HY		2017~2022	27
QPG-FS64VZ		2017~2018	28
QPG-FS65VZ		2017	10
QPG-FU64VY		2017	1
QPG-FU64VZ		2017~2018	10
QPG-FU65VZ		2017	3
QPG-FY64VY		2017	3
QDG-FQ62F	FUSOFIGHTER	2017	1
2PG-CD5BA	QUON	2018~2022	5
2PG-CD5CA		2017~2022	63
2PG-CD5CE		2019~2021	18
2PG-CG5BA		2018~2022	7
2PG-CG5CA		2017~2022	96
2PG-CG5CE		2018~2022	62
2PG-CW5CA		2019~2021	3
2PG-CX5BA		2018~2021	4
LKG-CD5ZA		2020	1
QPG-CD5ZA		2017	7
QPG-CD5ZE		2017	7
QPG-CG5YA		2017	1
QPG-CG5ZA		2017~2018	12
QPG-CG5ZE		2017	2
2RG-BSR90T2	CONDOR	2020	1
		TOTAL	2,544

We filed past recall report for this issue under notification number "5489" on June,12,2024, but we found insufficient in the measure.

We will expand the scope of the recall and carry out measures again.