

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5498	DATE	Jun.14.2024
MANUFACTURER	TOYOTA		
DESCRIPTION OF DEFECT	In windshield glass and backdoor glass, due to improper control of the adhesion process, there is a possibility that the adhesion strength between the glass and body panel may be insufficient. If the vehicle is operated continuously in this condition, water could enter inside the vehicle, and in the worst case, the glass can detach while driving.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	NOTE
6BA-MXUA80	[HARRIER]	2024	6	
6BA-MXUA85			1	
6AA-AXUH80			6	
6AA-AXUH85			1	
		TOTAL	14	