

VEHICLE SAFETY/ POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicle

CAMPAIGN No.	5502	DATE	June 24, 2024
MANUFACTURER	Komatsu Ltd.		
DESCRIPTION OF DEFECT	Some shovel loaders have non-genuine bearings assembled in the brake linkage. Therefore, repeated brake operations may cause the bearings to stick, making it difficult for the brake linkage to move. In the worst case, this may increase braking distance or cause the brakes to drag.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
YDS-WA130	「WA380-8」	2020-2024	250
YDS-WA129	「WA470-8」	2020-2024	13
		TOTAL	263