

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5493	DATE	June.28. 2024
MANUFACTURER	SHINMAYWA INDUSTRIES, LTD.		
DESCRIPTION OF DEFECT	With regard to bolts fastening the bumper of underrun protection device and stabilizer bracket which are installed on container carrier trucks equipped with detachable system, due to insufficient work instructions low structural grade bolts were used, hence there is a possibility that strength requirement is not satisfied.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2RG-FRR90S4	FORWARD	2024	127
2RG-FSR90S4		2024	6
2PG-FRR90S4		2024	2
2RG-FRR90S3		2024	1
2RG-FTR90U4		2024	1
2KG-FK62FZ	FUSO FIGHTER	2024	23
2KG-FK72FZ		2024	17
2KG-FK72F		2024	3
2KG-FK72FY		2024	3
2KG-FK62F		2024	2
2KG-FK62FY		2024	1
2KG-FD2ABA	HINO RANGER	2024	7
2KG-FE2ACA		2024	2
2DG-FE2ACA		2024	1
2KG-FJ2ACA		2024	1
2KG-GD2ABA		2024	1
2KG-XZU712M	HINO DUTRO	2024	1
		TOTAL	199