

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5509	DATE	Jul. 4 2024
MUNUFACTURER	Mitsubishi Fuso Truck and Bus Corporation		
DESCRIPTION OF DEFECT	On some heavy-duty touring buses, the tightening process for the steering wheel fixing bolts was improper, and some vehicles were shipped without the bolts installed. As a result, the steering wheel can come off the shaft.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2TG-MS06GP	「FUSO AERO ACE」	2017～2024	2,647
	「FUSO AERO QUEEN」	2017～2024	470
		TOTAL	3,117