

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	5504	DATE	2024/7/8
MANUFACTURER	KYOKUTO KAIHATSU KOGYO CO., LTD. Kyokuto Group Head Office Building, 2-5-11, Awajimachi, Chuo-ku, Osaka, Japan		
DESCRIPTION OF DEFECT	Due to insufficient design consideration, the direction indicators and emergency flashers mounted in the center of both sides of the container full trailer are too far from the front end of the vehicle. As a result, they do not comply with the standards of Article 41 and Article 41-3 of the Safety Standards.		

MANUFACTURER'S NAME	TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
TREX	FFB12402(modification)	full traler	8/3/2018-24/5/2023	45
TREX	FFS121AN	-	29/10/2012	1
TREX	FFS121AT	-	11/12/2012-9/1/2013	2
TREX	FFS121BD	-	19/12/2013-19/5/2015	2
TREX	FFS121BG	-	17/6/2014	1
TREX	FFS121BH	-	20/4/2015	2
TREX	FFS121BK	-	5/3/2015	1
TREX	FFS121BM	-	21/1/2016	1
TREX	FFS121BV	-	24/2/2016	1
TREX	FFS121BS	-	13/3/2016	1
TREX	FFS121CA	-	14/7/2016	1
TREX	FFS121CE	-	27/9/2016	1
TREX	FFS121CF	-	20/10/2016	1
TREX	FFS121CG	-	23/11/2016	1
TREX	FFS121CK	-	20/2/2017	1
TREX	FFS121CN	-	25/9/2017-2/11/2017	2
			TOTAL	64