

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/ Import Vehicles

CAMPAIGN No.	5513	DATE	Jul. 10. 2024
MANUFACTURER	Hino Motors, Ltd.		
DESCRIPTION OF DEFECT	On certain connecting devices of heavy-duty tractors, due to the inappropriate shape of the lock guard preventing incorrect connection, if the tractor and the trailer are connected while their height is not matched, the lock guard may not operate properly, causing them to be connected incorrectly. In addition, the coupler lock lamp indicating the completion of the connection may be illuminated in the meter. Therefore, the trailer may separate while running.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
QDG-SS1EKAA	[HINO Profia]	2013	1
QDG-SS1EKDA		2014～2017	5
2DG-SS1EKHA		2018～2021	14
		TOTAL	20