

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/ Import Vehicles

CAMPAIGN No.	5514	DATE	Jul. 10. 2024
MANUFACTURER	Kido Vehicle Industry Co., Ltd.		
DESCRIPTION OF DEFECT	In the coupling device of a large tractor, the shape of the lock guard that prevents incorrect coupling is inappropriate, so if the coupling operation is performed when the tractor and trailer are not at the appropriate height, the lock guard will not function properly, resulting in an incorrect coupling, and the coupler lock lamp in the meter, which indicates that the coupling is complete, may light up. Therefore, if you continue to use it without visually checking the coupling status, there is a risk that the trailer will separate while driving.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2KG-FV70HJR	Fuso Super Great	December 4, 2023	1
2DG-EXZ52CK	Giga	November 21, 2023	1
2DG-EW6ELH	Giga	October 20, 2023- April 22, 2024	18
		TOTAL	20