

# VEHICLE SAFETY RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5520	DATE	Jul. 11. 2024
MANUFACTURER	SUZUKI MOTOR CORPORATION		
DESCRIPTION OF DEFECT	The nuts fastening the front wheel hub and the driveshaft were improperly tightened. As the result, some of the nuts having insufficient tightening torque. If the vehicle is continued to be used as is, the nut may loosen, causing abnormal noise, and in the worst case, significant rattling may occur between the front wheel hub and the driveshaft.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES	NOTE
3BA-HA37S	ALTO	2024	3	
5AA-HA97S			1	
5BA-HE33S	ALTO LAPIN		6	
5BD-MK33V	SPACIA		1	
		TOTAL	11	