

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5505	DATE	July 18, 2024
MANUFACTURER	MITSUBISHI MOTORS CORPORATION		
DESCRIPTION OF DEFECT	Due to inadequate control programs in the navigation system, the liquid crystal screen may turn black or freeze in the event of a particular operation. Therefore, there is a risk that the camera image for the front and left side will not be displayed on the liquid crystal screen, and that it will not comply with the Safety standard Article 44 (criteria such as a posterior mirror). In addition, there is a risk that the rear camera image will not be displayed during receding vehicle, and some vehicles may fail to comply with Article 44-2 of the Safety Standard (a confirmation device immediately after a receding vehicle).		

T Y P E	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
5LA-GN0W	「OUTLANDER PHEV」	2021~2024	34,754
		TOTAL	34,754