VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5522	DATE	July 18, 2024		
MANUFACTURER	SUZUKI MOTOR CORPORATION				
DESCRIPTION OF DEFECT	The rear tire can develop cracking or deformation on tire tread. If it continues to be used, abnormal vibration is generated, and in the worst case, the tread may separate, affecting running stability.				

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
8BL-EM1BA	V-STROM 800DE	2023- 2024	661
		TOTAL	661