

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / ~~Import~~ Vehicles

CAMPAIGN No.	5508	DATE	JULY. 22. 2024
MANUFACTURER	NIPPON FRUEHAUF COMPANY LIMITED		
DESCRIPTION OF DEFECT	Due to inadequate confirmation at the time of design, the effective surface area of the rear surfaces of both sides of a 3-division type Rear Underrun Protective Devices are less than 420cm ² when installed on a vehicle with an overall width of 2,000 mm or more. Therefore, the device does not conform to Article 18-2 of the Safety Standards.		

TYPE		COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ISUZU	2RG-NMR88AN	ELF	2022-2023	3
ISUZU	2RG-NPR88AM	ELF	2023-2024	2
ISUZU	2RG-NPR88AN	ELF	2021-2023	45
ISUZU	2TG-NMR88M	ELF	2024	1
ISUZU	2TG-NPR88AM	ELF	2023-2024	4
HINO	2KG-XZU710M	HINO DUTRO	2024	2
HINO	2KG-XZU775M	HINO DUTRO	2021-2022	2
HINO	2RG-XZU710M	HINO DUTRO	2021-2023	13
HINO	2RG-XZU720M	HINO DUTRO	2021	2
TOYOTA	2RG-XZC710	TOYOTA DYNA	2021-2022	2
TOYOTA	2RG-XZU710	TOYOTA DYNA	2021	1
			Total	77