

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	5506	DATE	July 25, 2024
MANUFACTURER	Mitsubishi Logisnext Co., Ltd		
DESCRIPTION OF DEFECT	In the hydraulic motor that holds the position of the operator's compartment (cabin) of a fork loader, the motor may idle due to contamination or aeration in the hydraulic circuit. As a result, the cabin may slide on the rail and collide with the slide stopper during braking, and in the worst case, the slide stopper may break and the cabin may fall from the vehicle body.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
YDS-M18	「MR4531-3」	2018 - 2019	2
		TOTAL	2