

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5528	DATE	July.31.2024
MANUFACTURER	TOYOTA		
DESCRIPTION OF DEFECT	In the combination meter, due to an insufficient study of the illumination control program of the engine oil pressure warning light, the meter cannot receive an abnormal signal which is transmitted when oil pressure becomes low. Therefore, the engine oil pressure warning light will not illuminate.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	NOTE
6AA-ZVW60	[PRIUS]	2022-2024	8,586	U grade
6AA-ZVW65			1,249	
		TOTAL	9,835	