

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	5526	DATE	August 27, 2024
MANUFACTURER	Mitsubishi Logisnext Co., Ltd		
DESCRIPTION OF DEFECT	In forklift trucks with a maximum speed of 20 km/h or more, due to improper production instructions, the software settings of the vehicle control module may be incorrect, therefore the speedometer may not be displayed. (Violation of the Safety Regulations for Road Vehicles in Japan.)		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
EBT-F197	「H1F4」	2018 - 2020	2
EBT-F198	「HG1F4」	2022	1
		TOTAL	3