

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5534	DATE	September 12, 2024
MANUFACTURER	MITSUBISHI MOTORS CORPORATION		
DESCRIPTION OF DEFECT	Due to inadequate control programs in the navigation system, the liquid crystal screen may turn black or freeze in the event of a particular operation. Therefore, there is a risk that the camera image for the front and left side will not be displayed on the liquid crystal screen, and that it will not comply with the Safety standard Article 44 (criteria such as a posterior mirror.), also the rear camera image will not be displayed during receding vehicle, it will not comply with the Safety standard Article 44-2 (a confirmation device immediately after a receding vehicle).		

T Y P E	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3DF-LC2T	「TRITON」	2024	2,397
		TOTAL	2,397