

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles			
CAMPAIGN No.	5543	DATE	Oct 3, 2024
MANUFACTURER	Mazda E&T Co.,Ltd.		
DESCRIPTION OF DEFECT	Regarding the vehicle with a boarding slope device for wheelchairs, some rear seat belts were incorrectly assembled on the left and right sides during production due to improper work instructions. This may cause the vehicle's tilt sensor to malfunction, resulting in non-compliance with Article 22-3 of the Japanese safety standards.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
5AA-MK94S(revision)	Suzuki Spacia	2023 – 2024	92
5AA-MM94S(revision)	Mazda Flair Wagon	2024	9
TOTAL			101