

# VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5552	DATE	October. 3. 2024
MANUFACTURER	HONDA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	As for a power steering gearbox, when the gear engagement load is set inappropriately, the grease applied to the part where the gears engage is pushed out, increasing sliding resistance. This has risk of increasing the force required to operate the steering.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
5BA-RZ3	「ZR-V」	2022～2024	6,049
5BA-RZ5			1,592
6AA-RZ4			35,473
6AA-RZ6			16,222
5BA-FL1	「CIVIC」	2024	306
6AA-FL4		2022～2024	10,613
6BA-FL1		2021～2024	13,928
6BA-FL5		2022～2024	13,360
		TOTAL	97,543