

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.		DATE	
MANUFACTURER	YANMAR AGRIBUSINESS CO.,LTD.		
DESCRIPTION OF DEFECT	In a combine harvester, due to insufficient evaluation at the design stage of the sensor harness that detects when the driver is seated, there is a defect in the layout near the seat, which causes the harness to come close to moving parts. As a result, when the driver adjusts the seat position, the harness may get caught in the moving parts and be damaged, and in the worst case scenario, the key switch fuse may blow, causing the engine to stop and be unable to be restarted.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
－	「YH6115」	2022	36	
		2023	10	
		TOTAL		46