

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	5548	DATE	October 9, 2024
MANUFACTURER	ISEKI & CO., LTD.		
DESCRIPTION OF DEFECT	Due to improper manufacturing process, the spring pin that connects the parking brake pedal and the brake arm could come off completely and the parking brake could not work.		
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
—	FM575	2023-2024	60
	FM475	2023-2024	20
—	FM468	2023-2024	75
		TOTAL	155