第4号様式(英文リコール概要書) (第2関係)

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicies

CAMPAIGN No.	5556	DATE	2024/10/15	
MANUFACTURER	NIPPON TREX CO., LTD.			
	350 Minamiyamashinden, Ina-cho, Toyokawa ctiy, Aichi prefecture, Japan			
DESCRIPTION OF DEFECT	Due to insufficient analysis of vibrations in the fender stay of the dolly section on the van trailer with dolly, the fender stay lacks adequate strength. Consequently, vibration during driving may cause cracks in the fender stay, and in the worst case, the fender stay could break off along with the fender, potentially obstructing other traffic			

ТҮРЕ	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
TFA235AA		2020	1
TFA236AA		2023~2024	45
TFW234AA		2019~2020	3
TFW234AB		2021~2023	8
TFW235AA		2020	1
TFW237AA	-	2021	12
TFW237AB		2022	11
TFW237AC		2022	2
TFW237AD		2023	2
TFW237AE		2024	2
TFW237AF		2024	10
		TOTAL	97

(日本工業規格A列4番)