

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5587	DATE	November. 21. 2024
MANUFACTURER	HONDA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	As for the engine control computer, due to the inappropriate control program for the anti-wheelie function, when this function works upon re-acceleration after slowing down, it may not accelerate in response to the throttle operation as intended. For this reason, the vehicle circling while accelerating insufficiently may result in a fall.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
8BL-SD10	「CRF1100L Africa Twin」	2021～2023	755
8BL-SD15		2023～2024	437
		TOTAL	1,192