

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / ~~Import Vehicles~~

CAMPAIGN No.	5567	DATE	November 22, 2024
MANUFACTURE	VANTECH Inc. President and Representative Director Toru Sato		
DESCRIPTION OF DEFECT	Some MC4 connectors for solar panel connection have incomplete terminal construction due to improper manufacturing process. As a result, there is a risk of connector welding due to poor contact, which could lead to a fire in the worst case.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2DG- GDY281 改	CAMROAD	2024	16
		TOTAL	16