

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5585	DATE	December 12, 2024
MANUFACTURER	Mazda Motor Corporation		
	<p>On the parking assist unit, due to inappropriate processing the signal sent from the wheel-speed sensor, there may be discrepancy between the distance to the objects detected by ultrasonic sensor and the moving distance calculated using the signal from the wheel-speed sensor when reversing. As a result, the parking sensor indicator and the warning sound, which notify the driver of the obstacle position and distance, cannot function properly. The backward detect function of the smart brake support system cannot work, either. For the vehicle with automatic transmission, the control system to prevent unintentional start moving may fail to operate.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
5BA-ND5RE	「MAZDA ROADSTER」	2023-2024	6,817
5BA-NDERE			2,234
		Total	9,051