

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5588	DATE	December 12, 2024
MANUFACTURER	SUZUKI MOTOR CORPORATION		
DESCRIPTION OF DEFECT	Improper installation caused bending of the metal pipe portion of the hose assembly, placing the fuel feed supply hose assembly at risk of potential contact with the fuel vapor hose assembly. In the worst case, the fuel supply hose can be abraded to a degree that could cause a fuel leak from the hose.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
8BL-DU11N	BURGMAN	2022-2024	540
		TOTAL	540