

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No..	5599	DATE	December-27-2024
MANUFACTURER	PABCO CO.,LTD		
DESCRIPTION OF DEFECT	In large wing-body vehicles, insufficient consideration was given to the design of the installation position of the mount bracket that connects the chassis frame and the body, resulting in some bolts and nuts being installed in a state where the holes drilled for mounting the mount bracket overlapped with existing holes. As a result, the fastening force of the mount bracket to the chassis frame was not maintained and the nuts could loosen during use, and in the worst case scenario, the bolts and nuts could fall off while driving, endangering following vehicles, etc.		
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2PG-FS84VZ	FUSO SUPER GREAT	2024	21
		TOTAL	21