

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	5593	DATE	09 January 2025
MANUFACTURE	Hitachi Construction Machinery Tierra Co.,Ltd.		
DESCRIPTION OF DEFECT	In the internal spool of the hydraulic flow distribution valve (divider valve) installed in the steering circuit of a shovel loader, an incorrect spool was incorporated due to an inappropriate work process. Consequently, when surge pressure occurs within the divider valve during travel or other operations, the partition inside the valve housing may become damaged, leading to a sudden decrease in the amount of hydraulic oil flowing into the steering circuit. In the worst-case scenario, the handle may become abruptly heavy, making normal steering operations difficult.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	REMARK
YDN-H80	「ZW80S-5B」	2022	40	
YDN-8SDT15	「8SDT15」	2022	1	
		TOTAL	41	