

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	5606	DATE	28. Jan. 2025
MANUFACTURER	YAMAHA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	Regarding the front brake system, due to insufficient parts control during manufacturing, a wrong brake caliper was installed to some vehicles. Because of this, the brake pads cannot press the brake disc at the correct position. As the result, the braking force decreases, and in the worst-case scenario, the front wheel brake may become ineffective.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
8BJ-SEJ4J	CYGNUS GRYPHUS	2021~2024	13,260
		TOTAL	13,260