

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5604	DATE	Jan.30 2025
MUNUFACTURER	Mitsubishi Fuso Truck and Bus Corporation		
DESCRIPTION OF DEFECT	In some heavy-duty trucks, the balance weight is defectively welded to the propeller shaft due to improper welding methods. Therefore, the balance weight may fall off during running, possibly obstructing other traffic.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
2KG-FS70HZ	「FUSO SUPER GREAT」	2023~2023	9	
2KG-FU74HZ		2023~2023	8	
2KG-FV70GX		2023~2023	3	
2KG-FV70HX		2023~2023	12	
2KG-FV70HY		2023	1	
2PG-FS70HZ		2023~2023	6	
2PG-FS74GZ		2023~2023	4	
2PG-FS74HY		2023~2023	4	
2PG-FS74HZ		2023~2023	101	
2PG-FS75HZ		2023~2023	27	
2PG-FU74GY		2023	1	
2PG-FV70HX		2023~2023	4	
2PG-FV70HY		2023~2023	2	
2PG-FV70HZ		2023	1	
2PG-FV74HZ		2023~2023	5	
2PG-FY74HY		2023~2023	4	
		TOTAL	192	