

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

~~Domestic~~ / Import Vehicles

|                       |  |      |                    |
|-----------------------|--|------|--------------------|
| CAMPAIGN No.          | 5610   | DATE | February. 10. 2025 |
| MANUFACTURE           | Topre Corporation  |      |                    |
| DESCRIPTION OF DEFECT | <p>Due to insufficient consideration during the design of the front left chassis U-bolt washer (hereinafter referred to as the "U-bolt washer") of some refrigerated freezer vehicles, there is insufficient clearance between the hydrogen fuel tank and the U-bolt washer. Therefore due to vibrations while driving the hydrogen fuel tank and U-bolt washer repeatedly interfere with each other and if you continue to use the tank in this condition the hydrogen fuel tank may be damaged and in the worst case the engine may stop while driving</p> |      |                    |

| TYPE         | COMMERCIAL NAME | MODEL YEAR RECALLED | NUMBER OF VEHICLE |
|--------------|-----------------|---------------------|-------------------|
| 2RG-NPR88AN改 | ELF             | 2022~2024           | 21                |
|              |                 | TOTAL               | 21                |