

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

| | | | |
|-----------------------|--|------|---------------|
| CAMPAIGN No. | 5 6 1 4 | DATE | Feb. 13. 2024 |
| MANUFACTURER | N I S S A N | | |
| DESCRIPTION OF DEFECT | In the adaptive LED headlight control module, the presence of surrounding vehicles may not be detected correctly due to an inappropriate control program. Therefore, there is a risk that the place where the preceding vehicle or the oncoming vehicle is detected is irradiated with a high beam, although it is normally supposed to be irradiated with a low beam. | | |

| TYPE | COMMERCIAL NAME | MODEL YEAR RECALLED | NUMBER OF VEHICLES |
|------------------------|-----------------|---------------------|--------------------|
| 6 AA-SNT33 6 AA-T33 | X-TRAIL | 2024 | 3, 277 |
| | | TOTAL | 3, 277 |