

## VEHICLE SAFETY/ POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicle

CAMPAIGN No.	5615	DATE	February 19, 2025
MANUFACTURER	Komatsu Ltd.		
DESCRIPTION OF DEFECT	<p>In the control program of the HST valve of the hydrostatic transmission in the shovel loader, due to insufficient design considerations, the hydraulic pressure may be released at a lower pressure than commanded, resulting in the inability to perform shift control according to vehicle speed.</p> <p>Therefore, if the shift fails and acceleration occurs, the rotational speed measurement sensor of the HST motor pump detects an abnormality, triggers an error, and the transmission shifts to neutral, causing the vehicle to stop.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
YDS-WA142	「WA470-10」	2019-2024	62
TOTAL			62