

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicies

CAMPAIGN No.	5623	DATE	Mar 10 , 2025
MANUFACTURER	Isuzu Motors,Ltd Mazda Motor Corporation Nissan Motor Co.,Ltd. UD Trucks Corp. FURUKAWA UNIC CORPORATION		
DESCRIPTION OF DEFECT	In the operation status display device of the driver’s seat meter panel, if an abnormality occurs in the front or rear direction indicator because the setting of the auxiliary direction indicator is inappropriate, the number of blinks does not change and the driver cannot recognize the abnormality. Therefore, it does not comply with safety standards.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2PG-NPR88AM	Isuzu Elf	2024	1
2PG-NPR88YM		2024	3
2RG-NPR88AM		2023～2025	242
2RG-NPR88YM		2023～2024	107
2TG-NPR88AM		2023～2025	148
2RG-FRR90S4	Isuzu Forward	2024～2025	2
2TG-LPR88AM	Mazda Titan	2024	10
2RG-LPR88AM		2024	10
2RG-APR88AM	Nissan Atlas	2024	3
2RG-APR88YM		2024	1
2TG-APR88AM		2024	16
2RG-BPR88YM	UD Trucks Kazet	2024	1
		TOTAL	544