

**VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN**

Domestic/Import Vehicles

CAMPAIGN No.	5624	DATE	March. 6. 2025
MANUFACTURER	Kawasaki Motors, Ltd.		
DESCRIPTION OF DEFECT	On certain eligible units, the clutch release shaft was not properly welded between the lever and the shaft. Continuous use in this condition may result in the lever coming apart, making it difficult to disengage the clutch and thereby disabling the vehicle.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	Notes
8BL-EL400A	ELIMINATOR ELIMINATOR SE	2025	1369	
8BL-EX400L	Z400	2024	40	
8BK-EX250Y	Z250	2024	117	
		TOTAL	1526	