

VEHICLE SAFETY/ POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicle

CAMPAIGN No.	5620	DATE	March 10, 2025
MANUFACTURER	SAKAI HEAVY INDUSTRIES, LTD.		
DESCRIPTION OF DEFECT	Some fuel pumps for graders and road stabilizers have insufficient strength due to insufficient design study of the threaded part where the check valve is assembled. As a result, some of the threads cracked when the check valves were assembled, and in the worst case, fuel could leak out.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
YDS-1ER13	ER555F	2023 — 2024	38
YDS-1PM8	PM600	2023 — 2024	26
		TOTAL	64