

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/~~Import~~ Vehicles

| | | | |
|--------------------------|---|------|--------------|
| CAMPAIGN No. | 5622 | DATE | 12 Mar. 2025 |
| MANUFACTURE | MARUYAMA MFG.CO.,INC | | |
| DESCRIPTION OF DEFECT | In agricultural chemical spraying vehicles, the paint on the propeller shaft is in poor condition, and the tightening torque of the fastening bolts is low. If the vehicle is used in this state, the propeller shaft may fall off and the vehicle may become unable to drive or control. | | |

| TYPE | COMMERCIAL NAME | MODEL YEAR RECALLED | NUMBER OF VEHICLE |
|-----------|--------------------|---------------------------|----------------------|
| YDN-B204A | BSA-2000CH | 2023 | 18 |
| | BSA-2000CE | 2023 | 8 |
| | BSA-2000CHE | 2023 | 9 |
| | | TOTAL | 35 |