

# VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5 6 3 2	DATE	Mar. 27. 2025
MANUFACTURER	N I S S A N M T		
DESCRIPTION OF DEFECT	In the lithium-ion battery controller, the battery charge state cannot be accurately grasped due to an inappropriate control program. Therefore, the lithium-ion battery indicator displayed on the meter repeatedly increases and decreases. And continues to run in the same state, the e-POWER system warning light will turn on, and in the worst case, the output to the driving motor will be stopped by misjudgment as insufficient remaining battery level, which may result in the running out.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
6 AA-RP15 6 AA-SNP15	K I C K S	2 0 2 2 ~ 2 0 2 4	2 3, 2 4 7
		TOTAL	2 3, 2 4 7