

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5633	DATE	Mar.27 2025
MUNUFACTURER	Mitsubishi Fuso Truck and Bus Corporation		
DESCRIPTION OF DEFECT	<p>In the fuse box in the cab of some electric trucks, the design study of the circuit was inadequate. As a result, when the water pump's drive current increases due to its aging or emergency operation mode, a current exceeding the maximum allowable current of the connector terminals may flow.</p> <p>If the connector melts due to heat generation, a warning light (amber) will come on indicating an abnormality in the cooling system. In the worst case, the power supply to the VCU (vehicle control ECU) will be cut off, making the vehicle unable to drive.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ZAB-FEAVK	「FUSO eCANTER」	2023～2024	1,554
ZAB-FEB8K		2023～2024	62
ZAB-FEBVK		2023～2024	5
ZAB-FEC9K		2023～2024	3
ZAB-FED9K		2023～2024	22
		TOTAL	1,646