

# VEHICLE SAFETY RECALL CAMPAIGN IN JAPAN

## Domestic Vehicles

CAMPAIGN No.	5635	DATE	April. 3. 2025
MANUFACTURER	SUZUKI MOTOR CORPORATION		
DESCRIPTION OF DEFECT	<p>Due to the improper manufacturing process of the body control module which controls the power supply of the vehicle, the internal circuit may be damaged.</p> <p>Due to the above, the body control module may fail to be activated, if the vehicle is continuously used as it is, and engine may fail to be started in the worst case.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES	NOTE
4AA-MK54S	SPACIA	2024	1,745	
5AA-MK94S			4,494	
4AA-MM54S	FLAIR WAGON		131	
5AA-MM94S		2024～2025	370	
		TOTAL	6,740	