

# VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / ~~Import Vehicles~~

CAMPAIGN No.	5638	DATE	April 8, 2025	
MANUFACTURER	UD Trucks Corporation			
DESCRIPTION OF DEFECT	With regards to urea water tank chassis harness for tractors with GH13 engine, some harnesses were temporarily prepared with different waterproofing method according to the inappropriate work instruction. Due to insufficient waterproof of the harness, water may intrude to wires and cause corrosion. If the vehicle continues operation under these conditions, the conduction failure may occur, and warning lamp and buzzer may be activated, then the exhaust gas after-treatment system may become inoperable which might lead the NOx emission exceeding the standard level.			
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
2PG-GK6DAB	Quon	2023	2	
2PG-GK6DAD		2023	6	
2DG-GW6EAH		2023	40	
2DG-GW6ELH		2023	24	
2PG-EK6DAD	GIGA	2023	3	
2DG-EW6EAH		2023	1	
2DG-EW6ELH		2023	5	
		TOTAL	81	