

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	5642	DATE	Apr. 9. 2025
MANUFACTURER	Hino Motors, Ltd.		
DESCRIPTION OF DEFECT	On certain rear-hanging spare tire carrier brackets, because the bolts that secure the brackets to the vehicle body are not tightened properly, tightening torque may be insufficient. Therefore, the bolts can work loose due to vibrations while driving. And if the bracket is continued to be used in this condition, in the worst case, the bolts can fall off, causing the spare tire to fall off along with the bracket.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2SG-XKC605M	[Hino Dutro]	2024	67
2SG-XKU605M		2024	32
2SG-XKU645M		2024	4
2SG-XKU655M		2024	70
2SG-XKU710M		2024	62
2QG-XKU712M		2024~2025	61
2SG-XKU712M			
2QG-XKU722M		2024	8
2SG-XKU722M			
2DG-XZC605M		2023~2024	669
2KG-XZC605M			
2KG-XZC645M		2023~2024	77
2KG-XZC655M		2023~2025	389
2DG-XZC675M		2023~2024	75
2KG-XZC710M		2023~2024	236
2KG-XZU600E		2023~2025	211
2DG-XZU605M		2023~2024	742
2KG-XZU605M			
2KG-XZU640M		2023~2024	126
2KG-XZU645M		2023~2024	432
2KG-XZU650F		2023~2025	533
2KG-XZU650M			

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2KG-XZU652F	[Hino Dutro]	2023～2024	188
2DG-XZU655M		2023～2025	1, 191
2KG-XZU655M			
2DG-XZU675M		2023～2024	71
2DG-XZU685M		2023～2024	629
2DG-XZU695M		2023～2024	344
2DG-XZU710M		2023～2025	1, 897
2KG-XZU710M			
2DG-XZU712M		2023～2025	2, 310
2KG-XZU712M			
2DG-XZU720M		2023～2025	1, 135
2KG-XZU720M			
2DG-XZU722M		2023～2024	1, 443
2KG-XZU722M			
2KG-XZU730M		2023～2024	243
2DG-XZU732M		2023～2024	83
2KG-XZU732M			
2DG-XZU775M		2023～2024	383
2SG-XKC605	[Toyota Dyna 200]	2024	4
2SG-XKU605	[Toyota Dyna 300]	2024	3
2SG-XKU655	[Toyota Dyna 400]	2024	3
2SG-XKU710		2024	3
2QG-XKU712		2024	5
2SG-XKU712			
2SG-XKU722		2024	1
2DG-XZC605		2023～2025	988
2KG-XZC605			
2KG-XZC645		2023～2024	163
2KG-XZC655		2023～2024	144
2DG-XZC675		2023～2024	72
2KG-XZC710		2023～2024	145
2KG-XZU600H		2023～2024	21

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
2DG-XZU605	[Toyota Dyna 200]	2023～2025	630	
2KG-XZU605	[Toyota Dyna 300]			
2KG-XZU640	[Toyota Dyna 400]	2024	22	
2KG-XZU645		2023～2025	253	
2KG-XZU650		2023～2024	65	
2KG-XZU652W		2023～2024	30	
2DG-XZU655		2023～2025	537	
2KG-XZU655				
2DG-XZU675		2023～2024	73	
2DG-XZU685		2023～2025	145	
2DG-XZU695		2023～2025	179	
2DG-XZU710		2023～2025	675	
2KG-XZU710				
2DG-XZU712		2023～2024	430	
2KG-XZU712				
2DG-XZU720		2023～2024	205	
2KG-XZU720				
2DG-XZU722		2023～2025	536	
2KG-XZU722				
2KG-XZU730		2023～2025	47	
2DG-XZU732		2023～2024	30	
2DG-XZU775		2023～2025	97	
		TOTAL	19,217	