

VEHICLE SAFETY/ POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicle

CAMPAIGN No.	5640	DATE	May 9, 2025
MANUFACTURER	SAKAI HEAVY INDUSTRIES, LTD.		
DESCRIPTION OF DEFECT	Due to insufficient design consideration in the sub-engine control unit of road rollers, the automatic regeneration prohibition lamp may light up after a fault diagnosis, and automatic regeneration may not be possible.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
YDN-1R7	R2-4	2022 — 2023	113
YDN-1SW53	SW654	2022 — 2023	22
		TOTAL	135