

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5631	DATE	May 22, 2025
MUNUFACTURER	ANNEX Inc.		
DESCRIPTION OF DEFECT	Due to insufficient design consideration in the voltage stabilizer for spare batteries in camping vehicles (hereafter referred to as "regulators"), the distance from the regulator output to the fuse is long. As a result, when an abnormal current occurs, the current is not cut off, and in the worst case scenario, it may cause a fire.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
QDF-KDY231 改	CAMROAD	KDY231-8033098～8050354	86
LDF-KDY281 改		KDY281-0022789～0034084	113
2DG-GDY231 改		GDY231-0001964～0008144	16
2DG-GDY281 改		GDY281-0001637～0012309	304
		TOTAL	519