

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	5650	DATE	May. 27. 2025
MANUFACTURER	NIPPON FRUEHAUF COMPANY LIMITED		
DESCRIPTION OF DEFECT	The integrated light fixture on the rear side of a van-type truck does not comply with Article 37, Paragraph 3 of the Safety Standards because the tail light illumination part is mounted more than 400 mm from the outermost side of the vehicle due to negligence in checking the compliance with the standards for the mounting position when designing the van-type truck.		

TYPE		COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
UD TRUCKS	2PG-CD4CA	QUON	2022	1
UD TRUCKS	2PG-CD4FA	QUON	2023-2024	3
UD TRUCKS	2PG-CD5CA	QUON	2021	1
UD TRUCKS	2PG-CG5CA	QUON	2021-2022	2
UD TRUCKS	2PG-CG5CE	QUON	2021-2022	2
UD TRUCKS	2RG-CD5EA	QUON	2022	2
UD TRUCKS	2RG-CD5FA	QUON	2023	1
UD TRUCKS	2RG-CD5FE	QUON	2022	1
UD TRUCKS	2RG-CG5FA	QUON	2022-2023	2
			Total	15