

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5654	DATE	May 29,2025
MANUFACTURER	MITSUBISHI MOTORS CORPORATION		
DESCRIPTION OF DEFECT	Due to inadequate control programs in the navigation system, it may not be possible to boot, or repeated reboots may occur during use. Therefore, if the liquid crystal display does not display the camera image when checking the front and left side area of the vehicle or while reversing, the vehicle may not conform to safety regulations.		

T Y P E	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
5LA-GN0W	「OUTLANDER PHEV」	2021～2024	36,866
3DF-LC2T	「TRITON」	2024～2025	4,674
		TOTAL	41,540