

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5656	DATE	May. 29. 2025
MANUFACTURER	HONDA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	As for the emission diffusion prevention system, due to the inappropriate fixation of the LAF sensor cord, the cord interferes with the drive chain on some systems. For this reason, if the wire covering of the said cord is damaged, the vehicle may short-circuit, turning the warning light on, incapable of proper air-fuel ratio control, which resulted in the emission gas value exceeding the reference value.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
8BL-SC86	「CB1000 HORNET」 「CB1000 HORNET SP」	2024～2025	503
		TOTAL	503