

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5658	DATE	May 29, 2025
MANUFACTURER	SUZUKI MOTOR CORPORATION		
DESCRIPTION OF DEFECT	In the speedometer and odometer, moisture such as rainwater may enter the meter case due to insufficient waterproof performance. Therefore, if the vehicle is used continuously in this condition, the circuit board may be corroded, and the speed/odometer will not be displayed.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
8BJ-EA12J	AVENIS 125	2022-2024	6,919
8BJ-EA23M	BURGMAN STREET 125EX	2022-2024	6,492
8BK-EL11L	V-STROM 250SX	2022-2024	5,869
		TOTAL	19,280