

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN NO.	5661	DATE	June 12 ,2025
MANUFACTURER	ISUZU MOTORS LIMITED		
DESCRIPTION OF DEFECT	Due to inadequacy in its control program, the electric parking brake (EPB) may not operate, when the parking brake is engaged after rapid deceleration but before the vehicle comes to a stop, and the ignition is then turned off. Therefore, as the worst-case scenario, the parked vehicle may start moving against the driver's intention.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
TPG-NHR85AN□ TRG-NHR85AN	[ELF]	2017-2019	20
2RG-NHR88A□ 2RG-NHR88AN		2019-2022	3
TRG-NHS85AN		2017-2019	21
2RG-NHS88A□ 2RG-NHS88AN		2019-2024	13
TPG-NJR85AN□ TRG-NJR85AN□ TSG-NJR85PAN		2017-2019	15
2RG-NJR88A□ 2RG-NJR88AN□ 2SG-NJR88AN		2019-2023	605
TPG-NJS85AN□ TRG-NJS85A□ TRG-NJS85AN		2017-2019	4
2RG-NJS88A□ 2RG-NJS88AN		2019-2024	81
TPG-NKR85AN□ TPG-NKR85N		2017-2019	265
TKG-NKR85YN		2017	47

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2PG-NKR88N□ 2RG-NKR88A□ 2RG-NKR88AD□ 2RG-NKR88AN□ 2RG-NKR88N□ 2RG-NKR88R	[ELF]	2019-2023	3,573
2PG-NKR88YN□ 2RG-NKR88YN		2018-2023	751
TKG-NKS85AN□ TPG-NKS85AN		2017-2019	38
2PG-NKS88AD□ 2PG-NKS88AN□ 2RG-NKS88A□ 2RG-NKS88AN		2019-2024	228
TPG-NLR85AN□ TRG-NLR85AN□ TSG-NLR85PAN		2017-2019	1,861
2RG-NLR88AN□ 2RG-NLR88AR□ 2RG-NLR88N□ 2SG-NLR88AN		2019-2023	4,783
TPG-NLS85AN□ TRG-NLS85AN		2017-2019	198
2RG-NLS88AN		2019-2024	515
TPG-NMR85AN□ TPG-NMR85N□ TRG-NMR85AN□ TRG-NMR85N□ TSG-NMR85AN□ TSG-NMR85KAN		2017-2019	548
2RG-NMR88AN□ 2RG-NMR88AR□ 2RG-NMR88N□ 2RG-NMR88R□ 2SG-NMR88AN□ 2SG-NMR88N		2019-2023	977
TKG-NMS85AN□ TPG-NMS85AN		2017-2019	89
2PG-NMS88AN□ 2PG-NMS88AR□ 2RG-NMS88AN□ 2RG-NMS88AR		2019-2024	160
2RG-NNR88AR		2023	3

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2RG-NNS88AN	[ELF]	2024	1
TPG-NPR85AN□ TPG-NPR85N□ TRG-NPR85AN□ TSG-NPR85AN		2017-2019	794
TKG-NPR85YN□ TPG-NPR85YN		2017	162
2PG-NPR88AN 2PG-NPR88N 2RG-NPR88AN 2RG-NPR88AR 2RG-NPR88N 2SG-NPR88AN		2018-2023	1,235
2PG-NPR88YN□ 2RG-NPR88YN		2018-2023	999
TKG-NPS85AN□ TPG-NPS85AN		2017-2019	112
2PG-NPS88AN□ 2PG-NPS88AR□ 2RG-NPS88AN		2019-2024	330
2RG-NPR88AN kai	「—」	2022-2024	167
2RG-AHR88A	[ATLAS]	2021-2023	16
2RG-AHS88A□ 2RG-AHS88AN		2021-2023	4
2RG-AJR88A□ 2RG-AJR88AD□ 2RG-AJR88AN		2021-2023	4
2RG-AJS88A		2022	2
2RG-AKR88A□ 2RG-AKR88AD□ 2RG-AKR88N		2021-2023	11
2RG-AMR88AN		2022	1
2RG-APR88AR		2022-2023	3
2RG-APR88YN		2022	1
2PG-APS88AN		2022	1
		TOTAL	18,641

The Affected Parts Shipped As Repair Parts, But The Vehicles With Them Installed, Cannot Be Identified.

PARTS NAME	PARTS NO.	SHIPMENT YEAR	NUMBER OF VEHICLE
Electric Parking Brake Control Unit	8-97558203-0 8-98341609-2	2018-2025	6
		TOTAL	6