

VEHICLE SAFETY/ POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicle

CAMPAIGN No.	5668	DATE	June 26, 2025
MANUFACTURER	SAKAI HEAVY INDUSTRIES, LTD.		
DESCRIPTION OF DEFECT	<p>Due to inappropriate design drawings for the travel hydraulic pumps of pneumatic tired rollers and graders, some of the pump components (parallel keys) are insufficient in strength.</p> <p>As a result, the components (parallel keys) may break during operation, preventing the transmission of power and, in the worst case, causing the vehicle to become unable to travel.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
YDN-1TZ3	TZ704	2022 — 2025	519
YDS-1ER13	ER555F	2022 — 2025	94
		TOTAL	613