

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5672	DATE	Jun.27.2025
MANUFACTURER	TOYOTA		
DESCRIPTION OF DEFECT	<p>Due to inappropriate drawing dimensions for the rearview mirrors,</p> <p>#1there is a possibility that the left rearview mirror with a small radius of curvature on the mirror surface.</p> <p>#2 there is a possibility that an inner rearview mirror with a small mirror surface width in certain specifications.</p> <p>This condition would not meet structural requirement prescribed for a one-man bus.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ZBC-MUM1NAE	[SORA]	2018-2023	161
		TOTAL	161